



PATENT APPLICATION

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
YOSUKE MORIMOTO) Examiner: Bot L. Ledynh
Application No.: 10/600,766) Group Art Unit: 2862
Filed: June 23, 2003)
For: POSITION DETECTING)
APPARATUS, AND)
OPTICAL APPARATUS)
COMPRISING THIS AND)
POSITION DETECTING)
METHOD)
U.S. Patent No.: 6,873,148 B2)
Issued: March 29, 2005) December 1, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

12/05/2005 HALI11 00000094 6873148

01 FC:1811

100.00 OP

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

DEC 07 2005

Patentee's undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank L. Cire
Attorney for Patentee
Registration No.: 42,419

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 105722v1

DEC 6 7 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,873,148 *b2*

DATED : March 29, 2005

INVENTOR(S) : YOSUKE MORIMOTO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 24, "note" should read --not--.

COLUMN 10:

Line 37, "V," should read --V₀--.

COLUMN 12:

Line 51, "(T_{INIT}– T₀)" should read --(T_{INIT}– T₀)--.

Line 52, "(V_{INIT}– V₀)" should read --(V_{INIT}– V₀)--.

COLUMN 13:

Line 2, "T₀(k) < T < T₀(k+1)" should read --T_G(k) < T < T_G(k+1)--.

Line 3, "V₀(k) < V < V₀" should read --V_G(k) < V < V_G--.

Line 9, "(T– T₀)" should read --(T– T₀)--.

Line 9, "(V– V₀)" should read --(V– V₀)--.

COLUMN 18:

Line 12, "needs" should read --proceeds--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,148

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)

DEC 07 2005
→

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,873,148 *B2*

DATED : March 29, 2005

INVENTOR(S) : YOSUKE MORIMOTO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21:

Line 63, "(T_{INIT}– T₀)" should read --(T_{INIT}– T₀)--.

COLUMN 22:

Line 6, "T₀(k) < T < T₀(k+1)" should read --T_G(k) < T < T_G(k+1)--.

Line 10, "(T– T₀)" should read --(T– T₀)--.

Line 15, "gised" should read --gized--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,148

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30)

→ _____
DEC 7 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,873,148 *B2*

DATED : March 29, 2005

INVENTOR(S) : YOSUKE MORIMOTO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 24, "note" should read --not--.

COLUMN 10:

Line 37, "V," should read --V₀--.

COLUMN 12:

Line 51, "(T_{INIT}– T₀)" should read --(T_{INIT}– T₀)--.

Line 52, "(V_{INIT}– V₀)" should read --(V_{INIT}– V₀)--.

COLUMN 13:

Line 2, "T₀(k) < T < T₀(k+1)" should read --T_G(k) < T < T_G(k+1)--.

Line 3, "V₀(k) < V < V₀" should read --V_G(k) < V < V_G--.

Line 9, "(T– T₀)" should read --(T– T₀)--.

Line 9, "(V– V₀)" should read --(V– V₀)--.

COLUMN 18:

Line 12, "needs" should read --proceeds--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,148

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,873,148 *B2*

DATED : March 29, 2005

INVENTOR(S) : YOSUKE MORIMOTO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21:

Line 63, "(T_{INIT} - T_0)" should read --(T_{INIT} - T_0)--.

COLUMN 22:

Line 6, " $T_0(k) < T < T_0(k+1)$ " should read -- $T_G(k) < T < T_G(k+1)$ --.

Line 10, "($T - T_0$)" should read --($T - T_0$)--.

Line 15, "gised" should read --gized--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,148

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)

DEC 07 2005